## MAGILL SERVICES, INC.

137 Elk Drive

Murrells Inlet, SC 29576

## Tel (843) 652-7000 Fax (843) 652-7002

www.magillservicesinc.com

**OLL 18030** 

Date: May 18, 2020 Test Report # 200413

## BAINBRIDGE INTERNATIONAL, INC.

255 Revere Street Canton, MA 02021

Subject: One (1) sample of material tested for **Flame Resistance** in accordance with **NFPA 701, Test Method 2.** 

Identification: PO# 17699 Product Code: CG2572DP (DOM: May 2020, Lot: 88780-1)

Testing Completed: May 18, 2020

TEST, UNIT OF MEASURE	<u>RESULTS</u>	<b>REQUIREMENTS</b>
Flame Resistance (NFPA 701-Chapter 14) Test Method 2 - Fold		
After flame, seconds	0.0	
	0.0	
	0.0	
	1.3	
Average:	0.3	2.0 Maximum Individual
Char length, inches	10.4	
	9.4	
	11.2	
	9.4	
Average:	10.1	41.3 Maximum Individual
Dripping and flaming, seconds	1.6	
	0.7	
	0.5	
	0.5	
Average:	0.8	2.0 Maximum

The sample tested above **meets** the requirements outlined in Chapter 15 of NFPA 701 Test Method 2.

I certify that the above tests were performed under my supervision in accordance with the specification test requirements and that the reported test results are true, valid and applicable to the samples tested. I further certify that these samples are the only samples tested from the lot of components identified above.

Edward L. Magill Jr.

President

This report is for the exclusive use of the client to whom it is addressed and its communication to any others or use of the name Magill Services, Inc. must receive our prior written approval. This report is applicable only to the sample or samples tested.